

Function	Basic tools for ICT engineers
Spring force gauge	<u>HFG-50</u>
Receptacle insertion	SEW-050 / SEW-075 / SEW-100
Probe insertion	<u>INS-UNI</u> / <u>INS-050-0.6</u> / <u>INS-075-0.7</u> <u>INS-100-1.1</u>
Broken probe extraction	<u>BPET-102</u> / <u>BPET-135</u> / <u>BPET-165</u>
Receptacle extraction	<u>DRET-132-50</u> / <u>DRET-167-50</u> / <u>DRET-200-50</u>
Wire Wrapping	<u>WSU-30M</u>
Contact cleaning	PreciBrush PB-5
Case	Transparent plastic (RCEL175)

